


產品尺寸圖 (DIMENSION)



Symbol	Dimensions In Millimeters			Dimensions in Inches		
	Min	Nom	Max	Min	Nom	Max
A	2.15	2.35	2.55	0.085	0.093	0.100
A1	0.05	0.15	0.30	0.002	0.006	0.012
b	-	0.40	-	-	0.016	-
C	-	0.25	-	-	0.010	-
D	12.40	12.70	13.00	0.488	0.500	0.512
E	7.40	7.65	7.90	0.291	0.301	0.311
e	-	1.27	-	-	0.050	-
H	10.00	10.45	10.75	0.394	0.411	0.423
K	-	0.50	-	-	0.020	-
L	0.60	0.80	1.00	0.024	0.031	0.039
α	0°	-	8°	0°	-	8°
β	-	45°	-	-	45°	-

Note : QC. Inspection Range : A,A1,b,C,D,E,H

PACKAGE	SOP-20(300mil)	
DRAWING NUMBER	DIM-SOP20-0510-B	
SIGNATURE	製圖	莊立德
	審核	陳德文
	核准	汪可震